


924
NUMBER: _____
8-10-76
DATE: _____



Dokorder, Inc.

HI-FI COMPONENTS

5430 ROSECRANS AVENUE • P.O. BOX 8 • LAWNDALE, CA 90260 • (213) 644-4421

SERVICE BULLETIN

MODEL 1140

SUBJECT: Rec. Indicator Lamps

The lamps will explode, if excessive voltage is applied to the rec. indicator lamps.

This may happen, in the leads connected to no. 8 & J terminals of the multi-sync board connectors (CN-12,13) are cut by sharp edges of the top panel.

Re-shape the edge of the panel if it is sharp with a file.

